



1

ZUS16G



$\varnothing$  M4x10

**2x**




**2x**



**2x**

3



The diagram illustrates two assembly steps. The top part shows a screw being driven into a bracket. A screwdriver is shown turning the screw clockwise, indicated by a curved arrow. The screw is being inserted into one of the two circular holes in the bracket. The bottom part shows a cap screw being inserted into a tube. A dashed line indicates the alignment of the cap screw with the hole in the tube.

