





1




M05











M04



1






M04





QS19


KOLEJNOŚĆ MONTAŻU
IMOSRODOW.
THE FITTINGS SEQUENCE OF THE
CAMS.
DIE MONTAGEABFOLGE VON
EXZENTERN.

- 1  1A
1B
x6
- 2  x4
- 3  $\varnothing 8 \times 36$ x4


(A)




(B)




①




②



③



④



⑤

